Quality Control- Certificate

NAME OF THE WORKS : Drilling of 7 no's of borewell & fixing of pump motor and necessary accessories at Abbigere, Shettyhalli, Medarahalli, in different locations, ward no.12, in Settyhalli sub division

Job No : 012-14-000049.

Work Order no : EE/DD/WO/311/13-14 Dt : 04/03/2014

****

On verification of the inspection report of Technical Team deployed for this purpose generally the work executed is satisfactory. As such compliance of Quality Control Test reports as per MORT&H at this stage is not feasible, since this work was executed more than one years back.

30/4

Executive Engineer
Dasarahalli division
BBMP, Bangalore